63



HOELSCHER

WEATHERSTRIP MANUFACTURING CO., INC.

2400 S. Persimmon St., Tomball, Texas 77375 * Phone 713-869-6466 * Fax 713-869-6469 * Door Fax 713-861-2909

Wood Entry Door Collection Warranty

Hoelscher Weatherstrip Mfg. Co., Inc. offers a limited warranty for one (1) year on all wood doors from the original date of installation of the door. This warranty assures that each such door, for this period, is of good material and workmanship, and free from defects rendering the door unserviceable or unfit for the ordinary, recommended use. This warranty shall be void if the door has not been stored, installed, and maintained in a good workable manner. If the door is installed unfi nished, the warranty is void unless the door is sealed within a 72 (seventy two hour) period. During this period, if the door is exposed to rain or any water infiltration, the warranty shall be void. Additionally, all 6 sides of the door (front, back, edges, top, and bottom) must be properly finished and maintained or the warranty is void.

Conditions not Considered Defects Covered by the Hoelscher Warranty

The following conditions are not considered defects which are covered under the Hoelscher warranty: warp (as defined and within the limits prescribed below); bow or misalignment of the frame or jamb in which the door is hung; variation or unsatisfactory results in the surface checking of the wood; damage resulting from the causes beyond the control of Hoelscher (within the limits pre-scribed below); defects from failure to perform normal home owner maintenance or from attempts by non-Hoelscher workmen to repair the door; surface checks on the door that are less than 1/32" in width or less that 2" in length; panel movement or shrinkage of 3/16" or less (temperature, humidity, and direct sunlight may cause the wood panels on your door to shrink slightly, leaving an unstained line in the panel. This movement is normal and the door's construction is designed to allow this movement.); damage caused by the installa-tion of a storm door; leakage in the speakeasy opening in doors with such a feature (with or without decorative iron grille); reducing the height of the door by removing more than one (1") inch from the bottom rail and/or one-half (1/2") inch from the top rail of the door; reducing the width of the door by removing more than one-half (1/2") inch from the stiles at either side. Warp, as mentioned above, is defined as any distortion in the door itself, and does not refer to the frame or jamb in which it is hung. However, the term, "warp" shall not include the related terms of "bow", "cup", or "twist." To be considered warped for the purposes of the warranty; the distortion would have to exceed ¼" on a 6'8" tall door and ½" on an 8'0" tall door. Doors wider than 36 inches or taller than 8 feet are not warranted against warp. If the claimed nonconformity is warp, Hoelscher may defer repairing or replacing the product for up to twelve (12) months from the date of the claim of the date when the products was installed, as it is not uncommon for temporary warp conditions to occur as the door adjusts to local humidity and temperature. The aforementioned damages caused by forces beyond Hoelscher's control include, but are not limited to, damage caused by misuse, abuse, accident, mishandling, fire, flood, earthquake, storm, tornado, or other acts of nature. In addition to the above, the Hoelscher warranty does not cover any damages including fading of finish, discoloration, rust or flaking resulting from exposure due to installation without sufficient roof overhang protection, which causes the door to be exposed to an unusual amount of sunlight and /or precipitation. Minimum roof overhang is one in which the roof overhang projects out a distance from the structure no less than one-half (1/2) of the elevation between the bottom of the door and the base of the overhangs highest point above the entryway.

Prefinished Doors

Hoelscher Weatherstrip Mfg. Co. offers a twelve (12) month warranty on all of our prefinished doors. The warranty period begins on the original date of purchase.

Glass Panels

Hoelscher Weatherstrip Mfg. Co. does not warrant any product against glass breakage or glass damage for any reason.

"IG" Insulated Glass Panels

Your insulated glass panel is warranted for a period of two (2) years from the original date of installation. It is warranted against any material obstruction of vision through the unit due to accumulation of dust, moisture, or film on the internal surfaces caused by the failure of the unit's edge seal due to defects in material or workmanship under normal conditions. This warranty shall be void if; the unit is installed in high moisture environments (such as greenhouses or swimming pool enclosures) or film, shades, blinds, or any foreign materials, are used on or near the surface of the unit.

Claim Procedures and Limit on Remedies

All warranty claims must be presented within the warranty period for the specific product as outlined above. Hoelscher will not honor warranty claims made prior to payment in full for the warranted product. Upon validation by Hoelscher of any warranty claim, Hoelscher will at its option: 1) Repair the product and return it FOB our Houston, Texas facility, freight collect: 2) furnish a compa-rable replacement product (or if the product is no longer produced, a replacement which, in the sole opinion of Hoelscher, constitutes a comparable replacement) FOB our Houston, Texas facility, freight collect: 3) Refund the purchase price paid by the original purchaser of the product by Hoelscher. Hoelscher Weatherstrip Mfg. Co., Inc. reserves the right to inspect, in the field or on our premises, any product which is alleged to be defective, and must be given a thirty (30) day opportunity to have any door which is subject of a warranty claim field inspected by a company or field representative of Hoelscher.